

Re: FW: CQA Letter Report and Figure Showing Area Recommended for MSW Placement

Stephen Tyahla to: Whelan, Joseph

04/01/2011 05:18 PM

"lene.ichinotsubo@doh.hawaii.gov",

Cc: "Steven.chang@doh.hawaii.gov", "Miyashiro, Thomas", Bret Moxley, Steve Armann, Rich Vaille, Steve Wall

From: Stephen Tyahla/R9/USEPA/US

To: "Whelan, Joseph" < JWhelan1@wm.com>

Cc: "lene.ichinotsubo@doh.hawaii.gov" <lene.ichinotsubo@doh.hawaii.gov>,

""Steven.chang@doh.hawaii.gov" <Steven.chang@doh.hawaii.gov>, "Miyashiro, Thomas" <thomas.miyashiro@doh.hawaii.gov>, Bret Moxley/R9/USEPA/US@EPA, Steve Armann/R9/USEPA/US@EPA, Rich Vaille/R9/USEPA/US@EPA, Steve

Wall/R9/USEPA/US@EPA

EPA has reviewed the subject and attached documents and approves them with respect to the approval necessary under our Administrative Order on Consent ("Order") of 25 January 2011 to allow disposal in the area indicated in the figure provided.

We look forward to receiving the CQA report for the remaining E6 containment system repairs which should fulfill WMH's Work requirement specified in paragraph 19.f. of the Order.

Stephen F. Tyahla, P.E.,CHMM
Project Manager, RCRA Corrective Action Office
Waste Management Division
U.S. EPA Region IX
75 Hawthorne Street (WST-5)
San Francisco, CA 94105
Ph. 415.972.3466 / Fax 415.947.3533
tyahla.stephen@epa.gov

[This email, including any attachments, may contain non-public, privileged and/or confidential information solely intended to be conveyed to the designated recipient(s). If you receive this email and are not an intended recipient, please delete this email and its attachments immediately. The unauthorized use, dissemination, distribution, or reproduction of this email and its attachments is strictly prohibited by law.]

FW: CQA Letter Report and Figure Showing Area Recommended for MSW Placement

Greetings all.

Subject:

Please find the CQA report documenting the liner repairs related to the storm damage located within the northwest portion of Cell E6. We would appreciate your timely review and approval of this report. Currently we expect to have consumed available airspace by end of day today, Friday April 1st, and therefore request that approval to utilize the area described in this report today. We expect to provide you with the CQA report for the final portion of the repair to

the northwest area on Monday April 4th. Thank you in advance for your assistance with this most important project.

Best regards,

Joe

From: Boyle, Ron [mailto:Ron.Boyle@aecom.com]

Sent: Friday, April 01, 2011 12:14 PM

To: Whelan, Joseph

Cc: Frey, Jesse; Lottig, Justin; Frerich, Dan

Subject: CQA Letter Report and Figure Showing Area Recommended for MSW Placement

Aloha Joe,

Please find attached our Liner Damage Assessment, Repair and CQA Report for recent repairs on the MSW Cell E6 Sideslope Liner. Also attached is a figure showing the recommended MSW filling area in Cell E6.

Please let me know if you have any questions.

Thank you.

Ron Bovle, P.E.

Senior Engineer, Environment D 808.356.5321 Cell 808.497.5941 ron.boyle@aecom.com

AECOM Technical Services

1001 Bishop Street, Suite 1600 Honolulu, HI 96813 T 808.523.8874 F 808.523.8950 www.aecom.com

Waste Management recycles enough paper every year to save 41 million

trees. Please recycle any printed emails. MSW Placement_040111.pdf



Letter Report Cell E6 West Slope Repair_4-1-11.pdf